

BUILDINGS OF HISTORICAL & ARCHITECTURAL INTEREST SADDLEWORTH LOCAL LIST RECORD

List No.	3-014
Area	DIGGLE 3
Township	SADDLEWORTH
Property Name & Address	Brook Dene, 162 Huddersfield Road
Grid Ref.	SE 00130 07620
Surveyor	A. Schofield, 2011
Photo	2011



Current Use

1 Dwelling

Description of Building: age, style, notable/original features, significant alterations, general state of repair.

House part of the once Liberal Club using combinations of stone, brick and claddings. 2 storey, 1bay, double depth. E20C. Accrington brick and rendered 1st floor. Tile roof (renewed) brick ridge stack. Front elevation: gable end with arched doorway, overlight with stained glass with semi- circular lead covered wooden hood; in-filled doorway ground floor; 1st floor proud thin string above which 2 narrow windows, 3 sandstone quoins in brick corner pedestals; courses of stepped brickwork to arch of gable which is weather-boarded. Side elevation: to left small window, remainder proud with 3 windows with sandstone mullions, ornate yellow brick pattern below and splayed brick tiled lintels; remainder obscured behind 20C garage; 1st floor small window and 2 sets of 2 windows; all decorated as front. Good repair. splayed tiles slippage.

Interesting features of the surroundings of the building/ its setting?

Joined to single storey Liberal Club. 1950-1960s Occupied by station masters. Garage late addition. 1950-60s wooden general store to right demolished. Replaced with brick build house. Water trough opposite

Mapping evidence

Not on 1894 OS map : Mapping *Saddleworth* I, M. Buckley et al, SHS 2007

